



Advanced Hyperfine Products, Inc.
16644 Roscoe Blvd. Bldg 1c
Van Nuys, CA 91406
Phone: 661-313-8050

Email: bert@GoAHP.com

Step by Step Procedures

Documentation supporting installation of MLG Door Strut Assembly if requested or required by the aircraft owner or operator is outlined below.

STEP 1:

Obtain the following documents from www.GoAHP.com and www.FAA.gov websites for the Hawker MLG Door Strut Assembly part number 25UM781-23A/SS.

1. FAA Part's Manufacturing Approval, Supplement No. 1 (AHP website)
2. Advanced Hyperfine Products; Instructions for Continued Airworthiness, dated February 26, 2015. (AHP website)
3. FAA Form 337, Major Repair and Alteration (FAA website)
4. Instructions for completing the FAA Form 337, if you are not familiar with completing the Form 337. (FAA website)

As of February 26, 2015, the latest FAA Form 337 could be downloaded from this link:
<http://www.faa.gov/forms/index.cfm/go/document.information/documentID/185675>

STEP 2:

Complete the FAA Form 337 using the instructions and attach the following documents for submittal to your local FAA office.

1. AHP's FAA-PMA Supplement No. 1 (download from AHP website)
2. AHP's Instructions for Continued Airworthiness (also download from AHP website)
3. FAA 8130-3 Airworthiness Tags (I.D. tag that came with the parts)

STEP 3:

Complete any additional aircraft documentation or entries required per aircraft owner operator maintenance requirements.

The above procedures have been reviewed and are applicable as of Feb 26, 2015. Call or email me at Bert@GoAHP.com if you have any questions.

Regards,

Bert Brache
661-313-8050