



PMA Manufacturer since 1995



PMA Rod End Bearing p/n 32UM781-01

ONE PART REPLACES ALL OEM BEARINGS!



Replacement for: RMRE05UCBB,
RMVV05UCBB, RBJ341DHA483,
RMVV05UCBB4, RMVV5UCBB,
and AGS3080DHA483 bearings

Replacement Parts



The only part you need to carry in your inventory. FAA Parts Manufacturing Approval (FAA-PMA) is online and shows this rod end bearing not only replaces 6 OEM rod end bearings but it goes on 18 different Hawker aircraft models.



The only difference is the price!

**Buy
PMA**

www.LoopPMA.com

Order online or call us today!

661-313-8050

21618 Golden Triangle Road #106
Santa Clarita, CA 91350
info@LoopAerospace.com